

航空機騒音自動測定装置による測定結果

(三沢飛行場周辺)

上段: 単位(WECPNL)

下段: 騒音発生回数

【平成23年4月】

No.	測定位置	1日	2日	3日	4日	5日	6日	7日	8日	9日	10日	11日	12日	13日	14日	15日
①	飛行場内(西)	84.7 39	75.9 15	72.5 20	87.9 83	83.8 67	89.6 74	86.5 49	90.3 38	78.1 8	78.3 11	91.4 59	94.2 83	93.9 82	93.6 82	92.7 86
②	飛行場内(東)	88.3 60	79.6 21	77.7 32	88.4 98	86.7 83	90.6 89	84.3 62	84.3 29	71.2 5	79.3 13	86.7 63	93.7 104	89.3 111	88.5 113	92.0 49
③	(三沢市淋代)	59.9 8	57.6 5	47.4 1	67.3 21	66.7 17	62.4 15	64.1 23	58.2 7	52.0 2	53.0 1	62.5 9	61.9 13	64.6 24	69.7 35	62.8 17
④	防衛省行政財産内 (三沢市四川目)	地震の影響で機器破損														
⑤	(三沢市岡三沢)	57.7 6	51.7 4	60.6 4	72.1 42	67.0 34	75.1 39	68.8 16	76.7 28	58.3 4	52.0 3	78.8 32	80.6 60	77.1 44	74.7 49	75.4 28
⑥	(三沢市鹿中)	60.2 13	54.5 2	53.6 4	57.5 7	65.6 6	62.2 10	60.1 15	65.6 16	50.4 2	56.2 4	63.9 21	64.4 25	65.5 22	64.8 33	69.6 26
⑦	(東北町大字大浦字 淋代)	68.3 30	58.9 6	60.7 7	72.5 33	70.0 28	73.3 42	73.5 38	74.7 22	63.6 4	62.3 8	72.5 26	78.6 44	77.6 44	78.7 39	73.8 35
⑧	(東北町大字大浦字 東道ノ上)	65.7 13	55.4 2	57.2 3	72.4 25	63.7 20	74.3 25	63.3 17	69.4 10	43.1 1	63.4 3	70.9 22	75.2 31	71.0 22	75.9 27	72.4 21
⑨	(東北町大字大浦字 沼端)	67.6 18	64.4 5	61.9 2	64.8 25	61.5 15	68.4 26	68.7 24	68.9 17	-	58.5 4	69.0 20	76.8 37	74.1 29	72.4 25	67.2 20
⑩	(東北町大字大浦字 上久保)	52.9 4	61.2 3	50.0 1	60.3 4	48.1 2	54.3 3	63.2 8	59.7 4	53.2 4	56.0 4	52.4 3	58.5 4	-	48.1 2	61.1 10
⑪	(東北町字後久保)	59.6 8	53.8 2	61.9 2	54.4 3	44.4 1	56.7 5	57.7 10	54.4 4	49.9 3	65.5 5	69.6 11	66.4 20	66.0 15	65.7 18	66.3 15
⑫	(三沢市岡三沢)	65.4 18	67.7 35	64.6 16	77.2 73	74.9 58	79.7 70	74.2 23	79.2 42	61.7 3	64.2 6	81.0 47	85.6 94	81.6 75	79.3 74	80.9 54

No.	測定位置	16日	17日	18日	19日	20日	21日	22日	23日	24日	25日	26日	27日	28日	29日	30日
①	飛行場内(西)	63.9 4	60.7 3	91.6 143	89.3 84	94.7 149	96.7 134	89.5 76	90.1 7	95.9 13	99.2 137	98.1 118	84.4 59	99.4 96	95.5 48	64.0 5
②	飛行場内(東)	77.7 7	67.8 3	96.8 117	94.0 78	97.9 147	95.4 126	95.7 70	73.1 5	75.9 7	93.5 153	89.5 158	94.1 58	87.4 116	86.3 68	86.9 11
③	(三沢市淋代)	43.3 1	47.0 1	64.2 21	59.7 14	74.0 27	73.2 32	60.4 16	-	-	70.6 47	76.5 58	53.0 3	74.4 42	71.6 29	50.5 2
④	防衛省行政財産内 (三沢市四川目)	地震の影響で機器破損														
⑤	(三沢市岡三沢)	57.5 3	52.0 1	80.2 92	78.8 55	82.8 85	83.8 110	77.8 40	55.9 3	78.6 10	79.0 79	79.0 78	72.9 36	79.5 65	78.9 48	-
⑥	(三沢市鹿中)	60.6 1	45.7 1	73.7 61	71.2 34	76.8 90	75.3 67	71.3 25	46.2 2	60.4 3	74.6 56	70.2 53	66.7 15	67.8 50	67.5 35	-
⑦	(東北町大字大浦字 淋代)	54.5 3	50.1 2	69.7 54	65.6 58	78.8 71	78.0 60	65.7 63	61.1 1	79.5 10	78.8 68	79.3 65	57.5 13	81.2 47	80.9 24	50.4 3
⑧	(東北町大字大浦字 東道ノ上)	52.9 3	43.2 1	72.4 36	67.5 64	75.8 69	76.5 52	67.4 68	64.1 2	79.8 6	72.5 46	74.1 31	61.1 31	73.9 31	71.1 12	47.1 2
⑨	(東北町大字大浦字 沼端)	-	-	67.5 16	56.7 6	73.9 37	73.8 32	54.8 5	51.1 2	73.1 5	71.9 40	70.5 36	-	74.9 32	66.4 7	-
⑩	(東北町大字大浦字 上久保)	43.4 1	-	61.8 20	72.4 73	68.3 48	68.8 25	68.6 62	61.7 6	-	67.4 8	63.9 6	65.8 39	52.7 2	65.7 6	48.5 2
⑪	(東北町字後久保)	47.3 2	-	63.1 18	52.6 3	67.6 17	67.6 20	55.4 4	47.8 1	53.6 1	65.9 32	60.8 16	50.0 3	59.0 15	57.9 4	43.7 1
⑫	(三沢市岡三沢)	58.9 6	52.9 5	83.2 105	82.5 68	87.3 134	87.1 123	82.7 55	61.4 7	86.0 5	81.1 103	81.1 100	77.6 46	82.4 81	80.6 55	45.1 1