

鹿屋飛行場周辺の航空機騒音状況

鹿屋飛行場周辺に設置している自動騒音測定装置による測定結果は、次のとおりです。

令和3年6月

上段：Lden 中段：WECPNL 下段：騒音発生回数

| 測定点 No. | 測定場所 | 1日 (火) | 2日 (水) | 3日 (木) | 4日 (金) | 5日 (土) | 6日 (日) | 7日 (月) | 8日 (火) | 9日 (水) | 10日 (木) | 11日 (金) | 12日 (土) | 13日 (日) | 14日 (月) | 15日 (火) | 16日 (水) | 17日 (木) | 18日 (金) | 19日 (土) | 20日 (日) | 21日 (月) | 22日 (火) | 23日 (水) | 24日 (木) | 25日 (金) | 26日 (土) | 27日 (日) | 28日 (月) | 29日 (火) | 30日 (水) |
|------------|--------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| 1 | 上野町公民館 (鹿児島県鹿屋市) | 53.9 | 55.2 | 45.7 | 55.4 | --- | 47.5 | 53.6 | 53.5 | 54.6 | 50.1 | 48.2 | --- | --- | 53.9 | 54.5 | 43.2 | 52.5 | 54.7 | --- | 43.2 | 54.1 | 53.6 | 48.5 | 47.0 | 49.9 | --- | --- | 54.7 | 52.0 | 52.1 |
| | | (69.2) | (70.5) | (57.9) | (69.1) | (---) | (61.9) | (67.9) | (67.3) | (69.0) | (65.2) | (63.5) | (---) | (---) | (68.8) | (69.1) | (57.4) | (67.0) | (68.5) | (---) | (58.3) | (68.5) | (68.5) | (63.5) | (60.3) | (64.1) | (---) | (---) | (68.6) | (66.2) | (67.1) |
| | | 67 | 102 | 9 | 58 | 0 | 18 | 70 | 45 | 93 | 46 | 39 | 0 | 0 | 76 | 101 | 5 | 75 | 100 | 0 | 10 | 110 | 90 | 34 | 14 | 27 | 0 | 0 | 73 | 45 | 79 |
| 2 | 新生市営住宅集会所 (鹿児島県鹿屋市) | 50.4 | 52.7 | 47.4 | 56.7 | --- | --- | 48.4 | 57.0 | 53.0 | 47.3 | 42.9 | --- | --- | 50.9 | 50.9 | 43.1 | 50.0 | 52.5 | 36.3 | --- | 51.4 | 46.8 | 56.4 | 59.0 | 58.5 | --- | --- | 56.6 | 58.0 | 44.7 |
| | | (64.1) | (66.2) | (60.8) | (70.5) | (---) | (---) | (61.4) | (70.1) | (66.3) | (61.3) | (55.9) | (---) | (---) | (64.5) | (64.6) | (56.6) | (63.0) | (64.9) | (51.5) | (---) | (64.3) | (60.0) | (70.4) | (73.1) | (72.5) | (---) | (---) | (69.5) | (72.5) | (57.4) |
| | | 28 | 38 | 10 | 58 | 0 | 0 | 17 | 109 | 51 | 23 | 7 | 0 | 0 | 22 | 25 | 5 | 22 | 44 | 1 | 0 | 40 | 14 | 90 | 128 | 158 | 0 | 0 | 72 | 112 | 11 |
| 3 | 鹿屋市下水処理センター (鹿児島県鹿屋市) | 51.4 | 52.0 | 44.0 | 55.5 | 50.9 | 47.2 | 53.5 | 57.0 | 55.5 | 48.3 | 49.3 | 48.9 | 44.6 | 51.2 | 49.7 | 49.8 | 52.1 | 52.1 | 49.1 | 46.7 | 48.8 | 52.3 | 54.8 | 55.5 | 55.3 | 53.0 | 40.1 | 47.4 | 54.7 | 48.7 |
| | | (65.5) | (66.2) | (57.5) | (71.2) | (66.1) | (61.5) | (68.0) | (71.3) | (68.8) | (61.2) | (62.8) | (64.8) | (59.2) | (64.6) | (64.5) | (65.4) | (65.8) | (66.3) | (64.8) | (61.1) | (62.4) | (66.0) | (70.9) | (73.5) | (70.8) | (68.9) | (54.5) | (61.7) | (70.0) | (62.4) |
| | | 24 | 25 | 2 | 14 | 1 | 2 | 14 | 18 | 21 | 8 | 19 | 5 | 2 | 21 | 13 | 6 | 17 | 21 | 2 | 2 | 9 | 19 | 20 | 11 | 29 | 10 | 1 | 4 | 33 | 17 |
| 4 | 岡泉公民館 (鹿児島県鹿屋市) | 50.4 | 52.1 | 39.2 | 48.3 | 44.7 | 32.7 | 47.1 | 50.6 | 51.1 | 48.8 | 51.3 | --- | 45.1 | 50.4 | 51.9 | 42.8 | 49.7 | 48.6 | 39.7 | 48.7 | 50.3 | 49.0 | 47.3 | 53.7 | 52.5 | 45.7 | 44.0 | 40.9 | 52.1 | 47.1 |
| | | (63.0) | (66.1) | (55.8) | (62.1) | (60.9) | (45.8) | (59.3) | (63.0) | (63.6) | (61.4) | (64.1) | (---) | (60.3) | (63.7) | (65.0) | (57.2) | (62.8) | (61.6) | (52.2) | (61.1) | (62.6) | (62.3) | (60.6) | (67.2) | (66.4) | (61.6) | (59.7) | (53.3) | (64.1) | (60.2) |
| | | 27 | 33 | 4 | 17 | 2 | 1 | 15 | 8 | 18 | 12 | 25 | 0 | 3 | 30 | 30 | 6 | 22 | 24 | 2 | 3 | 17 | 23 | 14 | 15 | 22 | 11 | 2 | 5 | 36 | 22 |

※数値は速報値です。後日、修正されることがありますので、データ利用の際はご注意ください。

お問い合わせ先
九州防衛局 企画部 防音対策課
092-483-8824